

FORM - E

(Form of report to be made to the competent authority by inspection authorities or officers appointed under other Acts under section 28 of the Tamilnadu Public Buildings (Licensing) Act 1965 (Tamil Nadu Act 13 of 1965) referred to in rule 7 of the Tamilnadu Public Buildings (Licensing) Rules 1966).

1) Name and Designation of inspecting: Er. P. N. Ramesh Baabhu, authority or officer appointed or having jurisdiction under any other Act or Law.

Collector Panel Engineer, Vellore District.

2) Location of the building inspected (Door number, Street number, Name of place, i.e. Corporation / Municipality / Panchayat Union / Township / Cantonment)

: Green Valley Matriculation School,

S.F. No. 698/4, Sathgar Village, Pernambut - 635810. Pernambut Town & Taluk. Vellore District.

3) Date of Inspection

: 07.03.2023

4) Purpose for which the building is used

: To run Matriculation School

: Ground floor 7382.00 sqft

: First floor 4391.50 sqft



Nature of Defects noticed

: Nil

Suggestions for rectifying defects

7) If in a dangerous condition, immediate:

steps recommended to be taken.

8) Period for which license is required

: 01.03.2023 to 28.02.2026.

Date: 08.03.2023

Proceedings of Vellore Dist. Collector R. Dist. 22218/2017 Signature of inspecting authority or officer appointed or having jurisdiction

Er. P.N. RAMESH BAABHU

B.E.M.Fech, M.Sc(ReV), MIE, FIV, FIGV, C.Eng(I), MITA, MICI

B.E.M.Tech,M.Sc(Rev),Mit.,FIV,FIGV,C.Eng(I),MITA,MICI.
Chartered Engineer (M-119935-6/99)
Govt. Approved Valuer (F-1410)
Regd. Valuer for Weelth Tax (C-1/443-99)
Approved Valuer for Immoration Properties (F-5636)
Regd. Engineer Class 1A (TN Poblic Buildings Act)
Panel Valuer for Italia NEPI 100L, IFC & HUDCO
TELL ASECCIANTES
Mobile: 94431 1900. Small: Iffressociantes@yahos.com